25X1

25X1

25X1

cysor_6

22 March 1956

MENORANDUM POR: Director of Material

SUB-JECT

- : Alterations for Room 538
- 1. In response to a Project request that Room 538 be surveyed for the security of handling code word material, from OCI inspected these quarters. He made the following physical security recommendations:
 - a. In addition to soundpress lowers on the doors, he suggested that a felt strip be placed around the door in order to seal off any crack between the door and the door frame.
 - b. The plywood and aluminum partition between the Operations Couter secretarial space and the Project Registry be sound preefed with accustic tile.
 - c. A belt lock be installed on the inside of the entrance to Room 536 and that a busser be installed on the outside.
 - d. A means be provided for locking the door into the briefing room and the door from the operations work area into the passage way leading to the briefing room.
 - e. A look be provided for the door into the illustrator's room.
 - f. Some means be previded for closing off the area between the sliding panels and the steel partition of the briefing room.
 - 2. It is requested that the appropriate individuals in the Real Estate and Construction be notified so that the proper action can be taken.

PCS/DCI/O/PCF/efm

Distribution:
Orig and 1-addresses
1-intelligence
1-Ope shreno
1-Addn shreno

000100100
